

25	Y	1
70	Λ	

25X1

## SECRET

(IN 35Ø84) PAGE	
-----------------	--

INSTALLATION AND BEST POSSIBLE SOLUTION APPEARS TO BE MOUNT INDEX ATTITUDE CASSETTE ON BRACKET HOLDING RECOVERY BEACON BATTERY, RATHER THAN ON PANORAMIC CASSETTE STRUCTURE.

- A. IT SHOULD ALSO BE NOTED THAT THIS AFFECTS INTERCHANGE-ABILITY OF INDEX ATTITUDE CAMERA SUBSYSTEM BETWEEN CORONA AND LAN-YARD PROGRAMS.
  - 5. REQUEST SYSTEMS ENGINEERING BE INFORMED ASAP ON THE FOLLOWING:
- A. CAN INTERCHANGEABILITY BETWEEN PROGRAMS BE MAINTAINED BY FROUIDING FILM TRANSPORT MODULES CAPABLE OF ACCEPTING
  SUPPLY SPOOLS FOR 600 FOCT LENGTH? 140 FOOT LENGTH FOR CORONA?
- B. DOES WISH TO COMMENT ON USE PHILOSOPHY?
- C. DO DIFFERENT OPERATING MODES BETWEEN PROGRAMS OFFER ANY DESIGN PROBLEMS FOR CAMERA SUBSYSTEM CONTROL?
- D. SINCE TIME WORD WILL BE ADDED FOR LANYARD, WHAT IS EFFECT ON CAMERA SUBSTIEM FOR CORONA?

END OF MESSAGE

SECRET